

CABLE SECRETARIAT DISSEMINATION  
PERSON/UNIT NOTIFIED

CLASSIFIED MESSAGE

TOTAL COPIES

ROUTING AND/OR INITIALS - SEEN BY

Approved For Release 2001/07/16 : CIA-RDP78-06505A000800080055-1

**SECRET**

(When Filled In)

GROUP 1  
EXCLUDED FROM AUTOMATIC  
DECLASSIFICATION  
DECLASSIFICATION

1	6
2	7
3	8
4	9
5	10

PD  
RE

ADVANCE COPY  ISSUED  SLOTTED

BY: \_\_\_\_\_ AT: \_\_\_\_\_ Z

DISSEM BY 4 PER #

ACTION Comm 8  RID COPY

REPRODUCTION OF THIS COPY PROHIBITED

INDEX:  YES  NO

CLASSIFY TO FILE NO. \_\_\_\_\_

X-REF TO FILE NO. \_\_\_\_\_

FILE RID  RET. TO

BRANCH

DESTROY  SIG.

INFO:

FILE, VR,

NE 8, LOGS 4

25X1A

25X1A

SECRET 181443Z MAR 68 CITE

110

18 MAR 68 72548

DIRECTOR

25X1A

25X1A

1. EXPERIENCING DIFFICULTY WITH CALCIUM DEPOSIT BUILD-UP  
IN ~~the~~ AIRCONDITIONING WATER COOLING TOWER. SUITABLE WATER  
SOFTENING UNIT LOCALLY AVAILABLE FROM ~~the~~ COMPANY FOR 700  
DOLLARS.

2. REQUEST PERMISSION TO PURCHASE AND INSTALL. FUNDS  
CAN BE MADE AVAILABLE.

SECRET

BT

25X1A

25X1A

~~Not acceptable. Looks like sales  
talk to laymen.~~  
~~Not enough info. for complete  
evaluation.~~

W/3/19

REC'D
C
DC
EX
C/RE
RO

File

Approved For Release 2001/07/16 : CIA-**SECRET**-0000800080055-1

25X1A	DISPATCH	CLASSIFICATION <b>SECRET</b>	PROCESSING ACTION
			MARKED FOR INDEXING
TO Chief [REDACTED]			NO INDEXING REQUIRED
INFO.			ONLY QUALIFIED DESK CAN JUDGE INDEXING
FROM Chief [REDACTED] <i>Acu</i>			MICROFILM
SUBJECT General - Logistics/Supply Specific - Request for Replacement Air Conditioners			
ACTION REQUIRED - REFERENCES			
<p><i>Vol/Log 20-7</i></p> <ol style="list-style-type: none"> <li>1. Attached is requisition 122-814-65 for 17 Air Conditioners, <u>2 ton</u>, 50/60 cycle.</li> <li>2. Of the above 17 Air Conditioners, 15 are replacements for units presently in use and certified by the Public Works Officer as uneconomically repairable. "In Use" units are at least 9 years old and will average \$65 to \$75 each to put in C-1 condition. The 2 additional units (making a total of 17) will be issued to Public Works for rotation as spares; thus, allowing a planned maintenance program.</li> <li>3. With the creation of [REDACTED] communications equipment and personnel have increased to a point that <u>3 1/4 ton</u> units are no longer efficient; therefore, 2 ton units are being requested as replacements for present units.</li> <li>4. Along with air conditioners, it would be appreciated if Headquarters would furnish an appropriate manufacturers list of recommended spare parts.</li> </ol>			
25X1A	[REDACTED]		
25X1A	[REDACTED]		
25X1A	COORD: [REDACTED]	ENG.	
25X1A	<p>Distribution: Orig. &amp; 2 [REDACTED] w/att. 1 [REDACTED] ng.</p> <p><i>7/87 2/6/64</i></p> <p><i>RECORDED</i> <i>SL REGISTRY</i></p> <p><i>EO 1.17</i></p> <p><i>C/REC</i> <i>DC/REC</i> <i>C/ACQ</i> <i>C/CE</i> <i>FILE</i> <i>AWG</i></p>		
25X1A	[REDACTED]		
25X1A	[REDACTED]		
CROSS REFERENCE TO		DISPATCH SYMBOL AND NUMBER. [REDACTED]	DATE 3 November 1964
GROUP I EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION		CLASSIFICATION <b>SECRET</b>	HQS FILE NUMBER (61)